

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




Fig. 1A




Fig. 1B

200  
↙




Fig. 2

300  
↙

<hr/>		
TE <u>306</u>		
<hr/>		
PGO <u>304</u>		
<hr/>		
BE	<u>310</u>	2nd layer
	<u>308</u>	1st layer
<u>302</u>		
<hr/>		

Fig. 3





Fig. 4



550 °C

500 °C

Fig. 5

ohms/square




Fig. 6






Fig. 7




Fig. 8